

# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

## **Inspection Report**

Supervisor A

## Minerals Regulatory Program November 8, 2007

Mine Name: New-6	Permit number: S270111
Operator Name: Alan Newman	<b>Inspection Date:</b> 10/25/200

Time: 11 PM AM

Inspector(s): Tom Munson Other Participants: none

Mine Status: active Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

#### **Purpose of Inspection:**

To determine if the site was active.

#### **Inspection Summary:**

The site was visited and three people were working on site. Mr. Dan Smith had visited the site the day before and therefore had GPS'ed the site and determined the disturbance at 3.2 acres exceeding there currently approved 3 acres. The site was being actively mined and was looked at for site layout and storage of hazardous materials. A fuel tank and another tank were on site and did not have any containment which needs to be implemented. The workers had changed the oil on pieces of equipment and there was a minor spill. The site appeared to be strung out and junk was skattered around the site in various areas. There was a crushing and grinding operation on site with several conveyors. The miners stated that they produced everything from boulders to crushed material

### **Conclusions and Recommendations:**

The main problems at the site that need immediate attention is the fuel storage needs containment for spills and oil changes of equipment needs to be done in a safe containment area. Overall site cleanup needs to occur. Since the site has expanded to 3.2 acres and is only bonded for 3 acres, the areas outside the 3 acres need to be bonded or cleaned up and seeded. It now becomes imperative these items are taken care of before the next inspection or a cessation order will be written and the appropriate enforcement actions taken .

Page 2 of 2

Inspection Date: 10/24/2007; Report Date: 11/8/2007

Mine Number: S/027/111

Inspector's Signature

Date:

**Directions to Site:** 

Head west from delta until you almost reach the Nevada border where you head north several miles to the site.

Inspector's tm:pb


cc:

Operator Photos and GPS

 $O:\\M027-Millard\\S0270111-New-6\\inspections\\insp-102407.doc$ 

NEW-6









SEMI TRAILER

















PALESS + WOOD DEBRIS



MISCENTANOUS DEBRY





Oil spice

